

Message Text

LIMITED OFFICIAL USE

PAGE 01 BUDAPE 00781 231219Z
ACTION FBOE-00

INFO OCT-01 EUR-12 ISO-00 A-01 /014 W
-----129362 232203Z /75
R 231040Z FEB 78
FM AMEMBASSY BUDAPEST
TO SECSTATE WASHDC 747

LIMITED OFFICIAL USE BUDAPEST 0781

FROM AMBASSADOR KAISER

E.O.11652: N/A
TAGS: ABLD, AFSP, AMGT, HU
SUBJECT: BUILDING RESTORATION- PROPERTY NUMBER OTH X02003

1. AS I INDICATED TO ASSISTANT SECRETARY THOMAS DURING MY VISIT TO WASHINGTON LAST FALL, I HAVE BEEN VERY CONCERNED ABOUT THE DETERIORATING CONDITION OF THE BUILDING ON THE PROPERTY USED FOR THE EMBASSY'S RECREATION CLUB. THE BUILDING HAS LACKED MINIMAL ADEQUATE MAINTENANCE OVER THE YEARS, ALTHOUGH IT IS HEAVILY USED BY THE AMERICAN STAFF AND IS A CENTER OF DIPLOMATIC SOCIAL ACTIVITY. FORTUNATELY, THIS DEPLORABLE STATE OF AFFAIRS BEGAN TO CHANGE LAST SUMMER. DURING MR. STANGE'S VISIT TO BUDAPEST IN CONNECTION WITH PREPARATIONS FOR THE PROPERTY NEGOTIATIONS, HE ADVISED THE REPLACEMENT OF THE ROOF, WHERE SEEPAGE HAD CAUSED CONSIDERABLE DAMAGE TO THE INTERIOR WALLS. THE EMBASSY PROCEEDED TO GET A BID FROM THE DSD CONTRACTOR, WHICH WAS \$13,000 TO BUILD A WOODEN PEAKED ROOF.

2. WHEN THE NEW ADMINISTRATIVE OFFICER ARRIVED IN JULY, HE WITHDREW THE ROOF CONTRACT ON THE GROUNDS THAT THE BID WAS UNREASONABLY HIGH. SHORTLY AFTER MY ARRIVAL, I GAVE THE RESTORATION OF THE BUILDING HIGH PRIORITY BECAUSE OF ITS IMPORTANCE TO THE WELLBEING AND MORALE OF EMBASSY
LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 BUDAPE 00781 231219Z

PERSONNEL AND ITS FREQUENT USE FOR REPRESENTATIONAL ACTIVITIES.

3. SUBSEQUENTLY A NEW CONTRACT WAS ARRANGED AND A PROPERLY SLOPPED CEMENT ROOF WAS BUILT WITH THREE PLY TAR ROOFING, NEW GUTTERS AND DRAINAGE. THIS WAS DONE BY A DSD APPROVED CONTRACTOR, UNDER THE SUPERVISION OF

CONSTRUCTION SPECIALIST ON THE EMBASSY STAFF, AT A COST OF \$8,000 OBLIGATED AND LIQUIDATED AGAINST FY 1977 FBO M&R FUNDS. THE WATER DAMAGE TO THE BUILDING HAS BEEN EFFECTIVELY ARRESTED AND THE INTERIOR WALLS ARE DRYING OUT.

4. THE NEXT STATE IS THE REPAIR OF DAMAGED AREAS. SPECIFICALLY WE SHOULD SEAL AND RELEVEL ALL FLOORS WITH A MINIMUM OF FOUR INCHES OF CONCRETE, TILE THE BATHROOM AREAS, CLEAN OFF OLD EXTERIOR STUCCO, SEAL AND RESTUCCO, SEAL HOLES ON INTERIOR WALLS AND REPLASTER AND REPAIR THE CEILINGS. THE WORK WOULD BE DONE BY A DSD CONTRACTOR, UNDER THE SUPERVISION OF AMERICAN CONSTRUCTION SPECIALISTS, ON THE EMBASSY STAFF. THE CONTRACTOR'S BID IS \$14,000. IN ADDITION, THE OLD PLUMBING AND ELECTRICAL WIRING SHOULD BE REPLACED (THE HOT WATER HEATER IS NOW BEYOND REPAIR). THIS CAN BE DONE BY THE EMBASSY'S OWN PLUMBERS AND ELECTRICIANS, WITH A COST OF MATERIALS OF \$1,500.

5. THE DEPARTMENT'S APPROVAL OF THIS RESTORATION PROGRAM AND AN ALLOTMENT \$15,500 FOR THIS PURPOSE WOULD BE GREATLY APPRECIATED.
KAISER

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 23 feb 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978BUDAPE00781
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780084-0897
Format: TEL
From: BUDAPEST
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780224/aaaaatxo.tel
Line Count: 85
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 0a6c9ed1-c288-dd11-92da-001cc4696bcc
Office: ACTION FBOE
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 05 may 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: N/A
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 3510661
Secure: OPEN
Status: NATIVE
Subject: BUILDING RESTORATION- PROPERTY NUMBER OTH X02003
TAGS: ABLD, AFSP, AMGT, HU
To: STATE
Type: TE
vdkgvwkey: odhc://SAS/SAS.dbo.SAS_Docs/0a6c9ed1-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014